TPP SPS Project Deviation Report Project Summary Sheet	State Code 40 Project Code 01XX		
Project Classification Information			
N. 1 1	State of Province: Oklahoma		
□ Nort	h Atlantic North Central Southern Western		
Climate Zone: Dry-Freeze (☑ Dry-No Freeze ☐ Wet-Freeze ☐ Wet-No Freeze		
Colombia Classification:	Fine Grain Coarse Grain Active (SPS-8 Only)		
Project Experiment Classification Designation	on (SPS 1, 2 and 8): W		
Construction Start Date: April 1996	Construction End Date, 67.7		
FHWA Incentive Funds Provided to Agency	for this Project: Yes No		
Devi	ation Summary		
Site Location Deviations: 🗆 No De	viations Minor Deviations Significant Deviations		
Construction Deviations:	viations 🗹 Minor Deviations 🗆 Significant Deviations		
Data Collection and	d Processing Status Summary		
ПСот	plete Submission [Incomplete Data Not Available		
TAN Cabaduled Sar	nples Obtained and Tested Incomplete/No Test Data		
EVAIL Boggired	Data Obtained		
	Required Historical Estimates Submitted (SPS 5,6,7,9) quired Estimates Not Submitted		
Traffic Monitoring Equipment:	 ✓ WIM Installed On-Site ☐ AVC Installed On-Site ☐ ATR Installed On-Site ☐ No Equipment Installed 		
- 55 Manitoring M Preferred Contin	uous ☐ Minimum ☐ Below Minimum ☐ Site Related		
- Monitoring	Data Submitted C 10 Months		
FWD Measurements: Preconstru	ction Tests Performed Construction Tests Performed		
	Tests Performed W Post-construction Tests Performed		
Prome vicination	Tests Performed W Post-construction Tests Performed		
Distress fraction	onlete Submission [Incomplete Data Not Available		
Maint. & Renau. 24	nplete Submission 🗆 Incomplete 🗆 Data Not Available		
Fricholl Data.	Report Status		
	M Document Prepared M Final Submitted to FHWF		
Materials Sampling and Test I mis.	Document Prepared W Final Submitted to FHW		
Construction Report:	talled MAWS Installation Report Submitted to FHWA		
Page _ / of 5 Preparer			

LTPP SPS Project Deviation Report Site Location Guidelines Deviations	State Code Project Code	01XX 70		
☐ Comments Pertain to All Test Sections on Project ☐ Comments Pertain Only to Section(s): (Specify)				
Site Location Guideline Deviation Comments There were no cut/fill transitions within test				
sections. There are some sections are located in fill areas. This so	located in cut and hould not be a problem tructed on a planned	some at this site		
which already received earthwork of construction. Any settling which would done so.	occur should have all	ready		
	·			

Page 2 of 5 Preparer Justing Mach Date 12/10/97

LTPP SPS Project Deviation Report	State Code 40 Project Code 01XX			
Construction Guidelines Deviations Project Code				
Construction Guidelines Deviation Comments				
The second lift of ATB exc after an initial 6" lift. Two 6"	reeded the 4" maximum allowed			
after an initial 6 1.++. 140 6 sections,				

Page 3 of 5 Preparer Aunthy Martin Date 12/10/97

	Chan Code	40			
LTPP SPS Project Deviation Report	State Code Project Code	0.1 \times \times			
	Troject Com				
Materials Sampling and Testing Deviations					
Barrie to All Test Sections on Project	Waterials Start Sections on Project				
Comments Pertain to All Test Section(s): (Specify)					
ial Sampling and Testing Dev	riation Comments				
Data Collection & Material Sampling and Testing Deviation Comments					
	andia a limo-t	reated _			
The initial MSTP did not	U AC C	2112			
/	Use HU SUCHACE I	ager.			
The initial MSTP did not Subgrade or two mix types for These were corrected as specified by	FHWA and proper	labels			
These were corrected as specific	ad The edited M	ISTP is			
These were corrected as specified by FAWA and proper interest. For the additional samples were created. The edited MSTP is					
included in Appendix E of the 4001 Final Report.					
Montage					
	-				
	1				
		12/10/97			

Page 4. of 5 Preparer Junothy & Marks

Date 12/10/97

Deviation Report	State Code	40		
LTPP SPS Project Deviation Report Other Deviations	Project Code	<u> </u>		
Comments Pertain to All Test Sections on Project Comments Pertain Only to Section(s): (Specify)				
Other Deviation Comments				
There was not a WIM installed for the SPS-1. There is an existing one 5 miles away from the site that is collecting the neccessary data. Details pertaining to the WIM are in the				
is an existing one 5 miles away from	whe site that is	Localing		
The neccessary data. Details pertaining to the WIM are in the				
4001 Final Report.				

Page 5 of 5 Preparer Suntly Martin

Date 12/10/97